

Balliemeanoch Pumped Storage Hydro

Environmental Impact Assessment
Report

Volume 5: Appendices
Appendix 13.2: Cultural Heritage
Site Photographs

ILI (Borders PSH) Ltd

July 2024

Quality information

<u>Prepared by</u>	<u>Checked by</u>	<u>Verified by</u>	<u>Approved by</u>
<u>Jonathan Shipley</u> Associate Heritage Consultant	<u>Chris Moore</u> Associate Director	<u>Amy Jones</u> Technical Director	<u>David Lee</u> Technical Director

Revision History

<u>Revision</u>	<u>Revision date</u>	<u>Details</u>	<u>Authorized</u>	<u>Name</u>	<u>Position</u>
1	July 2024	Submission	DL	David Lee	Technical Director

Distribution List

<u># Hard Copies</u>	<u>PDF Required</u>	<u>Association / Company Name</u>

© 2024 AECOM Limited. All Rights Reserved.

This document has been prepared by AECOM Limited (“AECOM”) for sole use of our client (the “Client”) in accordance with generally accepted consultancy principles, the budget for fees and the terms of reference agreed between AECOM and the Client. Any information provided by third parties and referred to herein has not been checked or verified by AECOM, unless otherwise expressly stated in the document. No third party may rely upon this document without the prior and express written agreement of AECOM.

Table of Contents

1.	Cultural Heritage Site Photographs	1
	Photograph 1 Area of north dam looking south into the Headpond area (Loch Airiah visible in the distance).....	1
	Photograph 2 View across the northern dam area.....	2
	Photograph 3 Area of proposed access and compound at northern end of the Headpond.....	2
	Photograph 4 View into the Headpond area, with Loch Airigh at the centre) from highground to northwest.....	3
	Photograph 5 View of area to be used for small upper compound near unnamed lochan (NN 03738 16829).....	3
	Photograph 6 View across area proposed for upper compounds with the existing hydro scheme on the left, and Lochan Ròmach on the right.....	4
	Photograph 7 View across the existing hydro scheme and the area of the proposed compounds from Sròn Bhreac-liath.....	4
	Photograph 8: View across the area of the main dam from northwest to southeast.....	5
	Photograph 9: View into the main Headpond area, wit Loch Airigh at the centre, from the western end of the main dam.....	5
	Photograph 10: Photograph 10: View of Loch Airigh from the south, with the geological formation/ridge to its left.	6
	Photograph 11: View of the main Headpond area, with Loch Airigh right of centre, from the northeast.....	6
	Photograph 12: The Buinne Dhubh watercourse within the eastern limits of the Headpond area.....	7
	Photograph 13: Area of former shielings viewed from the northwest.....	7
	Photograph 14: Main cluster of former sheilings facing south.....	8
	Photograph 15: Main cluster of shielings facing northwest. Note the sheltered position, with Loch Airigh not visible in the background due to the topography.....	8
	Photograph 16: View towards the shielings on the western side of the watercourse.....	9
	Photograph 17: View towards the sheilings from the southeast. The structures are visible as stonework near the centre of the image, with the ground rising towards Loch Airigh on the right of the image.....	9
	Photograph 18: Possible marker cairn/stalkers windbreak (AECOM001).....	10
	Photograph 19: Possible upright stone located on a slight rise overlooking Buinne Dhubh watercourse viewed from the northeast (AECOM002).....	10
	Photograph 20: Possible upright stone located on a slight rise overlooking Buinne Dhubh watercourse viewed from the northwest (AECOM002).....	11
	Photograph 21: View of possible upright stone (centre) viewed from the highground to the north (AECOM002)..	11
	Photograph 22: Possible archaeological feature located on a small unnamed watercourse on the lower northeast slopes of Sròn Bhreac-liath (AECOM003).....	12
	Photograph 23: View of possible archaeological feature on the lower northeast slopes of Sròn Bhreac-liath from the east (AECOM003).....	12
	Photograph 24: Representative view of the existing forestry track to the northeast of the Development to be upgraded as an access track.....	13
	Photograph 25: Representative view of the existing forestry track on the alignment of the former Military Road (WoSAS 21742).....	13
	Photograph 26: Representative view of the existing forestry track to the northeast of the Development to be upgraded as an access track. The former drove road is documented as crossing at/near this point, but not evidence was noted (WoSAS 13857).....	14
	Photograph 27: Area of the former drove road (WoSAS 13857). All traces appear to have been removed by commercial forestry.....	14
	Photograph 28: General view across the lower slopes where the Tailpond and associated compounds will be located from the lower tunnel portal. Balliemanoch Farm is the white building in the centre.....	15
	Photograph 29: View towards Balliemanoch from the south, from the existing farm track near an area of post-medieval agricultural remains (WoSAS 96885).....	15
	Photograph 30: Area of post-medieval agricultural remains (WoSAS 96885), with more recent farm track. The Allt a'Gheataich burn runs through the woodland in the centre/right of centre of the image.....	16
	Photograph 31: View of the northern limits of the former settlement (WoSAS 1578) located within the southern corner of the temporary Construction Compound.....	16
	Photograph 32: Area of the temporary compound with the former settlement (WoSAS 1578) visible near the poles.....	17

Photograph 33: Better preserved settlement remains of the abandoned settlement to the south of the temporary compound and existing access (WoSAS 1578).	17
Photograph 34: View towards the Tailpond from Balliemanoch Chapel (SM4227).....	18
Photograph 35: View from the land above Balliemanoch Chapel. The supposed chapel is located in the hollow in the foreground.	18
Photograph 36: Large upright stone within the lower section of the scheduled area looking towards the Tailpond.	19
Photograph 37: View of the Tailpond works area.	19
Photograph 38: View of Temporary Compound area northwest of Balliemanoch Farm.....	20
Photograph 39: Carn Dubh Crannog (SM4175) viewed from Rubha nan Eun hheadland to the southeast.....	20
Photograph 40: Carn Dubh Crannog (SM4175) viewed from the west, with Rubha nan Eun headland on the right.	21
Photograph 41: Carn Dubh Crannog (SM4175) viewed from north, demonstrating the positioning of the crannog in the bay, and the protection Rubha nan Eun headland provides to the southeast.	21
Photograph 42: View from Rubha nan Eun headland towards the Development to the southeast.....	22
Photograph 43: Views to the southwest from the upper floor of Inveraray Castle (LB11552). Note views of the southern parkland, including Upper Avenue and Fisherland, are blocked due to tree cover and planting.	22
Photograph 44: Views to the northeast from the upper floor of Inveraray Castle (LB11552), with Dun na Cuaiche (LB11543) on the hilltop in the distance. Note views of the track proposed as the workers access are not possible due to tree cover.	23
Photograph 45: Building foundations from the Combined Operations Training Camp (WoSAS 87736) in Duchess Louise Wood.	23
Photograph 46: Section of the existing track, as it passes the foot of Dùn na Cuaiche, which will be temporarily upgraded to serve as a workers access track.	24
Photograph 47: Section of the existing track, as it passes the foot of Dùn na Cuaiche, which will be temporarily upgraded to serve as a workers access track, with a ha-ha on the southern side.	24
Photograph 48: Section of the existing track near Malt Land which will be temporarily upgraded to serve as a workers access track.....	25
Photograph 49: View from Dùn na Cuaiche (LB11543) across Inveraray Castle and the associated Garden and Designed Landscape (. Note the later 20th century development of Inveraray at the south side of Fisherland, and the inability to see Upper Avenue due to extensive.....	25
Photograph 50: Historic photo postcard (postmarked 1908) showing the view from Dùn na Cuaiche (LB11543). Note the limited woodland around Inveraray Castle, as well as the contained character of the town.....	26
Photograph 51: Historic photo postcard, undated but assumed to date to the 1920s, showing the view from Dùn na Cuaiche (LB11543). Note the increase in woodland around Inveraray Castle, as well as the growth of New Town to the south of Inveraray.	26
Photograph 52: Historic photo postcard, undated but assumed to date to the mid-20th century, showing the view from Dùn na Cuaiche (LB11543). Note the prominence of more mature woodland around Inveraray Castle, as well as the development of the southern Fisherland area.	27
Photograph 53: Memorial commemorating Gertrude Canning in the southern area of the Policies near Upper Avenue (WoSAS 66814).	27
Photograph 54: Representative photo of the southern end of Upper Avenue to be temporarily upgraded and used as a temporary access track.	28
Photograph 55: Upper Avenue near the quarry site (AECOM004), with possible loading bays in the woods on the righthand side of the image (AECOM005).....	28
Photograph 56: Northern end of Upper Avenue where the track joins the A819.	29
Photograph 57: Bealach an Fhuarain well-house (LB11520) located in woodland above Upper Avenue.	29
Photograph 58: Former quarry within the woodland above Upper Avenue (AECOM004). Site to be used as a temporary Construction Compound.	30
Photograph 59: View of the area of the proposed Temporary Marine Facility/Jetty.	30
Photograph 60: View of the proposed Temporary Compound at the southern limits of Inveraray Garden and Designed Landscape (GDL00223).....	31
Photograph 61: View from the cup marked stone 600m east-southeast of Keppochan (SM4186), looking north towards Loch Awe.....	31
Photograph 62: View from the cup marked stone 600m east-southeast of Keppochan (SM4186), looking south towards the Development.....	32

1. Cultural Heritage Site Photographs



Photograph 1 Area of north dam looking south into the Headpond area (Loch Airiah visible in the distance)



Photograph 2 View across the northern dam area.



Photograph 3 Area of proposed access and compound at northern end of the Headpond.



Photograph 4 View into the Headpond area, with Loch Airigh at the centre) from highground to northwest.



Photograph 5 View of area to be used for small upper compound near unnamed lochan (NN 03738 16829).



Photograph 6View across area proposed for upper compounds with the existing hydro scheme on the left, and Lochan Ròmach on the right.



Photograph 7View across the existing hydro scheme and the area of the proposed compounds from Sròn Bhreac-liath.



Photograph 8: View across the area of the main dam from northwest to southeast



Photograph 9: View into the main Headpond area, with Loch Airigh at the centre, from the western end of the main dam.



Photograph 10: Photograph 10: View of Loch Airigh from the south, with the geological formation/ridge to its left.



Photograph 11: View of the main Headpond area, with Loch Airigh right of centre, from the northeast.



Photograph 12: The Buinne Dhubh watercourse within the eastern limits of the Headpond area.



Photograph 13: Area of former shielings viewed from the northwest.



Photograph 14: Main cluster of former sheilings facing south.



Photograph 15: Main cluster of shielings facing northwest. Note the sheltered position, with Loch Airigh not visible in the background due to the topography.



Photograph 16: View towards the shielings on the western side of the watercourse.



Photograph 17: View towards the shielings from the southeast. The structures are visible as stonework near the centre of the image, with the ground rising towards Loch Airigh on the right of the image.



Photograph 18: Possible marker cairn/stalkers windbreak (AECOM001).



Photograph 19: Possible upright stone located on a slight rise overlooking Buinne Dhubh watercourse viewed from the northeast (AECOM002).



Photograph 20: Possible upright stone located on a slight rise overlooking Buinne Dhubh watercourse viewed from the northwest (AECOM002).



Photograph 21: View of possible upright stone (centre) viewed from the highground to the north (AECOM002).



Photograph 22: Possible archaeological feature located on a small unnamed watercourse on the lower northeast slopes of Sròn Bhreac-liath (AECOM003).



Photograph 23: View of possible archaeological feature on the lower northeast slopes of Sròn Bhreac-liath from the east (AECOM003).



Photograph 24: Representative view of the existing forestry track to the northeast of the Development to be upgraded as an access track.



Photograph 25: Representative view of the existing forestry track on the alignment of the former Military Road (WoSAS 21742).



Photograph 26: Representative view of the existing forestry track to the northeast of the Development to be upgraded as an access track. The former drove road is documented as crossing at/near this point, but not evidence was noted (WoSAS 13857).



Photograph 27: Area of the former drove road (WoSAS 13857). All traces appear to have been removed by commercial forestry.



Photograph 28: General view across the lower slopes where the Tailpond and associated compounds will be located from the lower tunnel portal. Balliemanoeh Farm is the white building in the centre.



Photograph 29: View towards Balliemanoeh from the south, from the existing farm track near an area of post-medieval agricultural remains (WoSAS 96885).



Photograph 30: Area of post-medieval agricultural remains (WoSAS 96885), with more recent farm track. The Alt a'Gheataich burn runs through the woodland in the centre/right of centre of the image.



Photograph 31: View of the northern limits of the former settlement (WoSAS 1578) located within the southern corner of the temporary Construction Compound.



Photograph 32: Area of the temporary compound with the former settlement (WoSAS 1578) visible near the poles.



Photograph 33: Better preserved settlement remains of the abandoned settlement to the south of the temporary compound and existing access (WoSAS 1578).



Photograph 34: View towards the Tailpond from Ballimeanoch Chapel (SM4227).



Photograph 35: View from the land above Ballimeanoch Chapel. The supposed chapel is located in the hollow in the foreground.



Photograph 36: Large upright stone within the lower section of the scheduled area looking towards the Tailpond.



Photograph 37: View of the Tailpond works area.



Photograph 38: View of Temporary Compound area northwest of Balliemanoch Farm.



Photograph 39: Carn Dubh Crannog (SM4175) viewed from Rubha nan Eun hdeadland to the southeast.



Photograph 40: Carn Dubh Crannog (SM4175) viewed from the west, with Rubha nan Eun headland on the right.



Photograph 41: Carn Dubh Crannog (SM4175) viewed from north, demonstrating the positioning of the crannog in the bay, and the protection Rubha nan Eun headland provides to the southeast.



Photograph 42: View from Rubha nan Eun headland towards the Development to the southeast.



Photograph 43: Views to the southwest from the upper floor of Inveraray Castle (LB11552). Note views of the southern parkland, including Upper Avenue and Fisherland, are blocked due to tree cover and planting.



Photograph 44: Views to the northeast from the upper floor of Inveraray Castle (LB11552), with Dun na Cuaiche (LB11543) on the hilltop in the distance. Note views of the track proposed as the workers access are not possible due to tree cover.



Photograph 45: Building foundations from the Combined Operations Training Camp (WoSAS 87736) in Duchess Louise Wood.



Photograph 46: Section of the existing track, as it passes the foot of Dùn na Cuaiche, which will be temporarily upgraded to serve as a workers access track.



Photograph 47: Section of the existing track, as it passes the foot of Dùn na Cuaiche, which will be temporarily upgraded to serve as a workers access track, with a ha-ha on the southern side.



Photograph 48: Section of the existing track near Malt Land which will be temporarily upgraded to serve as a workers access track.



Photograph 49: View from Dùn na Cuaiche (LB11543) across Inverary Castle and the associated Garden and Designed Landscape (). Note the later 20th century development of Inveraray at the south side of Fisherland, and the inability to see Upper Avenue due to extensive



Photograph 50: Historic photo postcard (postmarked 1908) showing the view from Dùn na Cuaiche (LB11543). Note the limited woodland around Inveraray Castle, as well as the contained character of the town.



Photograph 51: Historic photo postcard, undated but assumed to date to the 1920s, showing the view from Dùn na Cuaiche (LB11543). Note the increase in woodland around Inveraray Castle, as well as the growth of New Town to the south of Inveraray.



Photograph 52: Historic photo postcard, undated but assumed to date to the mid-20th century, showing the view from Dùn na Cuaiche (LB11543). Note the prominence of more mature woodland around Inveraray Castle, as well as the development of the southern Fisherland area



Photograph 53: Memorial commemorating Gertrude Canning in the southern area of the Policies near Upper Avenue (WoSAS 66814).



Photograph 54: Representative photo of the southern end of Upper Avenue to be temporarily upgraded and used as a temporary access track.



Photograph 55: Upper Avenue near the quarry site (AECOM004), with possible loading bays in the woods on the righthand side of the image (AECOM005).



Photograph 56: Northern end of Upper Avenue where the track joins the A819.



Photograph 57: Bealach an Fhuarain well-house (LB11520) located in woodland above Upper Avenue.



Photograph 58: Former quarry within the woodland above Upper Avenue (AECOM004). Site to be used as a temporary Construction Compound.



Photograph 59: View of the area of the proposed Temporary Marine Facility/Jetty.



Photograph 60: View of the proposed Temporary Compound at the southern limits of Inveraray Garden and Designed Landscape (GDL00223).



Photograph 61: View from the cup marked stone 600m east-southeast of Keppochan (SM4186), looking north towards Loch Awe.



Photograph 62: View from the cup marked stone 600m east-southeast of Keppochan (SM4186), looking south towards the Development.

